

BOARD MEETING DATE: 10/20/2026

ITEM NO: X-d

RECOMMEND THAT the Board approve the Annual Comprehensive Safety
Inspection Report.

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2026-2027

College Facility: <u>North Florida College</u> Fire District: <u>Madison</u>	# OF SERIOUS FIRE SAFETY VIOLATIONS <u>0</u>
SCHOOL / FACILITY: <u>Live Oak Center</u>	
ADDRESS: <u>210 Ohio Ave N, Live Oak, FL 32064</u>	
	# OF NON-SERIOUS FIRE SAFETY VIOLATIONS <u>0</u>

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION) _____	Jeb W. Bynum (Municipal Fire Safety Inspector)
	CONTRACTED COMM. COLLEGE BOARD FIRE SAFETY INSPECTOR NAME PRINTED _____
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION) _____	Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
	INSPECTOR ADDRESS & PHONE NUMBER _____
SIGNATURE DATE _____	9/19/2026
	FIRE INSPECTOR CERTIFICATION NUMBER <u>133209</u>

LOCATION:
Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES ___ NO

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

FACILITY ADMINISTRATOR NAME PRINTED <u>Glenn Strickland</u>	FACILITY ADMINISTRATOR SIGNATURE <u>Glenn Strickland</u>
FACILITY ADMINISTRATOR TITLE <u>Physical Plant Director</u>	SIGNATURE DATE <u>9-21-26</u>

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2026-2027

College Facility: North Florida College Fire District: Madison
SCHOOL / FACILITY: Main Campus
ADDRESS: 325 Turner Davis Drive, Madison, FL 32340

OF SERIOUS FIRE SAFETY VIOLATIONS 0

OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION) Jeb W. Bynum (Municipal Fire Safety Inspector) September 18, 2026
CONTRACTED COMM. COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION) Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
INSPECTOR ADDRESS & PHONE NUMBER

SIGNATURE DATE 9/19/2026 FIRE INSPECTOR CERTIFICATION NUMBER 133209
Jeb W. Bynum COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES NO

Approval of Reports by Board (Including Letter) YES NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

Glenn Strickland
FACILITY ADMINISTRATOR NAME PRINTED
Physical Plant Director
FACILITY ADMINISTRATOR TITLE

Glenn Strickland
FACILITY ADMINISTRATOR SIGNATURE
9-21-26
SIGNATURE DATE

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2026-2027

College Facility: North Florida College Fire District: Madison

SCHOOL / FACILITY: Perry Center

ADDRESS: 319 North Byron Butler Parkway, Perry FL 32347

OF SERIOUS FIRE SAFETY VIOLATIONS 0

OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)

Jeb W. Bynum (Municipal Fire Safety Inspector)
CONTRACTED COMM. COLLEGE BOARD FIRE SAFETY INSPECTOR NAME PRINTED

September 18, 2026
INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
INSPECTOR ADDRESS & PHONE NUMBER

SIGNATURE DATE

FIRE INSPECTOR CERTIFICATION NUMBER

9/19/2026
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

133209
FIRE INSPECTOR CERTIFICATION NUMBER

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES ___ NO

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

FACILITY ADMINISTRATOR NAME PRINTED

FACILITY ADMINISTRATOR SIGNATURE

FACILITY ADMINISTRATOR TITLE

SIGNATURE DATE

Glenn Strickland

Glenn Strickland

Physical Plant Director

9-21-26